

MEMORANDUM

To	Club Captains
From	Manager Lifesaving
CC	Club Secretaries, Presidents, BOM, LSEC
Date	Friday, 9 July 2021
Pages	1
Subject	Radios Season 2021-2022 - UPDATE

As an addendum to Friday 2nd July Memo - Radios Season 2021-2022, I would like to offer clarification on servicing and programming.

The two main reasons to radio non-compliance at last year's Gear Inspection was:

1. Physical damage / corrosion to the radios
2. Incorrect Profiles

Item 1 is self-explanatory and is rectified during servicing. Item 2 is where a lot of the confusion lies.

The correct profile from last season has 4 training channels. If the radio has these then it has the most current patrol profile.

- 58 Train
- 66 Train
- 67 Train
- 68 Train

These 4 channels should be in the Sydney or local zone in the radio.

If they are not, then we would suggest the radio has an old profile and needs to be re programmed.

If your club radios do not have these channels or you are unsure, then they should be sent away for re programming.

We hope that this clarifies and assists clubs.

Regards

Scott Muir

MANAGER LIFESAVING